



In case of blue LED R34 should be replaced with a jumper

TITLE				DefendLine1, MCU module			
FILE:				REVISION: 1.1 from 18.07.2010			
PAGE 1 OF 1				DRAWN BY: Dmity Pakhomenko			