



When using the ICSP the MCU is a slave. When running, the MCU is a master. Hence the discrepancy with the RFM69 pin names.