



Most holes are 3/16"

1/2" for wires  
to motors

1/2" for wires  
to motors

15/32" for the power switches

Adjust holes as needed in this area  
for the Servo and Motor Control  
boards.

5/16" for  
caster