

Trouble Shooting Feedback Noise Issue

If you are getting feedback noise when plugging in the Aux input cable into KAB-230 and KAB-250 Bluetooth amp boards, please cut the wire next to the empty slot on the 5-pin wire harness as shown in the picture below.

